Fuel System - Hard Start When Parked Downhill

NO: 23-31

DATE: 11-28-2007

MODEL/MODEL YR:

\$60 2001 -\$80 1999-2006 V70 2001-2007 V70XC, XC70 2001-2007 XC90 2003-

SUBJECT:

New Fuel Pump for Starting Problems when Parked Downhill

REFERENCE:

VIDA

Description

A vehicle may be difficult to start if it is parked facing downhill with a very small amount of fuel in the <u>fuel tank</u>. The vehicle will start normally if fuel is added to the tank or if the vehicle is moved to level ground.

Service

Old part no.	New part no.
30769013	31261128
30792852	31261127
30792854	31261130
30792857	31261133
30792859	31261135
30792861	31261137

A new style <u>fuel pump</u> has been introduced with an improved anti-siphon valve. If there is a customer complaint of this condition, use one of the new pumps as shown.

Note! See VIDA for exact <u>fuel pump</u> application.